

RoHS Consolidated Test Report

SAMPLE INFORMATION:

1. Sample Description: **STEPPER MOTOR**

2. Trade Mark:  **OEMOTOR**

3. Model: **OE57, OE20, OE28, OE35, OE36, OE39, OE42, OE57, OE60, OE86, OE57HSE, OE60HSE, OE86HSE, OE110HSE**

4. Serial/Batch No. of Sample:

5. Manufacturer Date:

6. Manufacturer: **OEMOTOR ELECTRIC CO., LIMITED**

Manufacturer Address: **Building B1, Hutang Industrial zone, Lingdao Rd, Wujin District, Changzhou, China.**

CLIENT INFORMATION:

1. Applicant: **OEMOTOR ELECTRIC CO., LIMITED**

Applicant Address: **Building B1, Hutang Industrial zone, Lingdao Rd, Wujin District, Changzhou, China.**

2. Applicant Post Code:

3. Applicant Telephone:

4. Verification method:

IEC62321:2008 /IEC62321-4:2013, IEC62321-5:2013

5. Results:

The material of the sample shown in this report do not exceed the required limit of EU RoHS 2011/65/EU.

REMARKS:

1. The test data obtained and the report issued by laboratories other than HTL are provided by the applicant to us for data consolidation purposes. The report shall not be reproduced in part without written approval of us.
2. Characterization & Condition of sample: Normal.
3. Ambient Condition During Testing: (15~25)°C (30~50)%RH
4. Date of Consolidated: Aug. 22, 2017

Approved by: _____

(Redly Zhang)



RoHS Consolidated Test Report

No.	Part Description	Issue Body	Report No.& Issue Date	Test Data(ppm)
01	Silver metal sheet	SGS	SHAEC1612739602 Date: 2016/06/16	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative
02	PVC wire enclosure (red)	SGS	CANEC1613825201 Date:2016/07/20	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative PBBs: N.D. PBDEs: N.D. DEHP: N.D. DBP: N.D. BBP: N.D. DIBP: N.D.
03	Black plastic ring	863 TEST	SAC2016-05880E 2016/07/28	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative PBBs: N.D. PBDEs: N.D.
04	screw	SGS	CANEC1605658101 Date:2016/04/12	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative
05	Green Plastic(wire insulation)	TUVRh	0144102545a Date:2016/05/23	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative PBBs: N.D. PBDEs: N.D.
06	Silvery metal (steel ball)	PTS	NB2016042133 Date: 2016/04/27	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative
07	Sheet iron	CTI	ECL01J009007001 Date:2017/02/27	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative

No.	Part Description	Issue Body	Report No.& Issue Date	Test Data(ppm)
08	Copper alloy(coil)	SGS	CE/2016/11403 Date:2016/01/15	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative
09	Blue plastic(wire insulation)	SGS	CANEC1414626501 Date: 2014/09/12	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative PBBs: N.D. PBDEs: N.D.
10	Black metal(Ferrite material)	863TEST	SAC2016-06474E Date:2016/08/24	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative
11	Yellow plastic	863TEST	SAC2016-03637E Date:2016/04/26	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative PBBs: N.D. PBDEs: N.D.
12	Aluminium plate with black paint	CTI	ECL01J009007001 Date:2017/02/27	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative
13	Slivery metal(Axle)	SGS	CANEC1522928101 Date:2016/01/06	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative
14	Translucent plastic	863TEST	SAC2017-02865 Date:2017/04/10	Cd: N.D. Pb: N.D. Hg: N.D. Cr ⁶⁺ : Negative PBBs: N.D. PBDEs: N.D.

Remark:

mg/kg = ppm, N.D. = Not Detected (<MDL) , Negative=Cr⁶⁺ Not Detected
END OF REPORT